Discovery Firmware Field Programming Discovery Firmware Field Programming

 Firmware Field programming is performed in the Training/Control Screen. Begin by clicking the "Data" tab, then choosing "Discovery Setup". PLEASE NOTE: You must be running the latest updated version of the Discovery software in order to update the Discovery Firmware.

2. When the "Discovery Hardware Module Maintenance" Window appears, click the "Check Module" Button.

🖄 Master Training/Control Screen - BrainMaster Discovery 1.5.8										
Data	Display	Freq.Bands	Color	Sound						
~	Use COM2 Use COM2 Use COM4 Use COM4 Use COM6 Use COM6 Use COM6 Playback F	L 2 3 4 5 5 7 3 5 7 3 5 7 3		sk:	00:00	Points:		0	Close	
> >	Low Freq (60Hz Noto 50Hz Noto Show Logi Eyes Open Discovery	Jata Cutoff Filter :h Filter :h Filter in Data N Setup								
	-									+

Discovery Hardware Module Maintenance							
IMPORTANT NOTICE:							
Do not use this control unless instructed to do so by BrainMaster Technologies, Inc.							
Inappropriate use of this control could cause you to have to return your device to the factory.							
Press Check Current Firmware Button when ready							
Status:	Waiting						
Device Serial Number:	100001						
Current Firmware Revision:	REV						
Available Firmware Revision:	REV						
Check Module	Close						

3. When the following box appears, click "OK" to continue. **PLEASE NOTE:** The text that appears might be different to the text that appears on your screen.



Discovery Firmware Field Programming

4. The following screen will you know your current firmware revision. Click "Yes" to continue.

5. The following window will give you instructions. Be sure to follow these instructions, and click "OK" to continue.

6. The "Discovery Hardware Module Maintenance" Menu will now begin to update the firmware. **PLEASE NOTE:** During this process, make sure that nothing else is to be occurring as this can cause problems in writing the Discovery Firmware. You can tell that this is occurring, because, the Status line number will be changing.

531-315 v1.0 6/9/2011





Discovery Hardware Module Maintenance									
IMPORTANT NOTICE:									
Do not use this control unless instructed to do so by BrainMaster Technologies, Inc.									
Inappropriate use of this control could cause you to have to return your device to the factory.									
Updating Firmware Please wait									
Writing Line: 194 of 1550 to DiscoveryLength: 43									
Serial Number: 60334									
first pass: 24 s1:1 s2:13 s3:-1 fw is: 24									
Revised Firmware Found									
Close									

7. When the following screen appears, click "OK" to continue. On the "Discovery Hardware Module Maintenance" menu, click "Close"



Page 2 of 2